



Solstice

Wash Instructions

Wet Cleaning

Use mild soap or detergent in warm water, not to exceed 160° F (synthetic setting). Use high water level with mild agitation. Extract gently. Do not bleach.

Dry Cleaning

Use short cycle of perchlorethylene or Stoddard solvent. Extract gently.

Drying

Air, cabinet or tumble dry low temperature. Do not exceed 3-5 minutes on synthetic cycle at maximum of 140° F. Hang or fold immediately after drying. For open weave draperies (such as casements, sheers and lenos) air or cabinet dry on pin frame or curtain stretcher.

Finishing

If necessary, press as follows: Hand iron at low heat setting (275°) with damp press cloth or steam iron with dry press cloth. Grid Heat Press; press for short intervals and with minimum steam. Do not lock head. Flat Bed Press: press dampened drapery using cloth covering.

Avoid prolonged contact with heat.

No finishing if fabric is re-hung at termination of drying cycle. Occasional light touch up with hand iron (275 degree Fahrenheit maximum) may be desired.